



Entergy Nuclear Northeast
Indian Point Energy Center
295 Broadway, Suite 1
P.O. Box 249
Buchanan, NY 10511-0249
Tel 914 734 5340
Fax 914 734 5718

Fred Dacimo
Vice President, Operations

October 14, 2003

Re: Indian Point Unit No.2
Docket No. 50-247
NL-03-155

Document Control Desk
U.S. Nuclear Regulatory Commission
Mail Stop O-P1-17
Washington, DC 20555-0001

Subject: Licensee Event Report No. 2003-005-00
Automatic Reactor Trip due to Reactor Coolant Pump Trip on Under-Frequency Caused by a Degraded Off-Site Grid

Dear Sir:

Entergy Nuclear Operations, Inc. (Entergy) hereby submits the attached Licensee Event Report (LER), 2003-005-00, in accordance with 10 CFR 50.73. This event is of the type defined in 10 CFR 50.73 (a)(2)(iv)(A) and 10 CFR 50.73(a)(2)(i)(B) for an event recorded in Entergy's Corrective Action Process as Condition Reports CR-IP2-2003-05176 and - CR-IP2-2003-05296 respectively.

Entergy is making no new commitments in this LER. Should you have any questions regarding this submittal, please contact Mr. John McCann, Manager, Licensing, Indian Point Energy Center at (914) 734-5074.

Sincerely,

A handwritten signature in black ink, appearing to read "Fred R. Dacimo".

Fred R. Dacimo
Vice President, Operations
Indian Point Energy Center

Attachment

cc: see next page

IE22

**cc: Mr. Hubert J. Miller
Regional Administrator, Region 1
U.S. Nuclear Regulatory Commission
475 Allendale Road
King of Prussia, PA 19406-1415**

**Mr. Patrick D. Milano, Sr. Project Manager
Project Directorate I
Division of Licensing Project Management
U.S. Nuclear Regulatory Commission
Mail Stop O-8-C2
Washington, DC 20555-0001**

**INPO Record Center
700 Galleria Parkway
Atlanta, GA 30339-5957**

**Resident Inspector's Office
U.S. Nuclear Regulatory Commission
Indian Point Unit 2
P. O. Box 38
Buchanan, NY 10511-0038**

**Mr. Paul Eddy
Public Service Commission
3 Empire State Plaza, 10 Fl
Albany, NY 12223-1350**

LICENSEE EVENT REPORT (LER)

(See reverse for required number of
digits/characters for each block)

Estimated burden per response to comply with this mandatory information collection request: 50 hours. Reported lessons learned are incorporated into the licensing process and fed back to industry. Send comments regarding burden estimate to the Records Management Branch (T-6 E6), U.S. Nuclear Regulatory Commission, Washington, DC 20555-0001, or by Internet e-mail to bis1@nrc.gov, and to the Desk Officer, Office of Information and Regulatory Affairs, NE08 0202 (3150-0104), Office of Management and Budget, Washington, DC 20503. If a means used to impose information collection does not display a currently valid OMB control number, the NRC may not conduct or sponsor, and a person is not required to respond to, the information collection.

1. FACILITY NAME

Indian Point Unit 2

2. DOCKET NUMBER

05000- 247

3. PAGE

1 OF 4

4. TITLE

Automatic Reactor Trip due to Reactor Coolant Pump Trip on Under-Frequency Caused by a Degraded Off-Site Grid

5. EVENT DATE

MO DAY YEAR

08 14 2003

6. LER NUMBER

YEAR SEQUENTIAL
NUMBER

2003 - 05 - 00

7. REPORT DATE

MO DAY YEAR

10 14 2003

8. OTHER FACILITIES INVOLVED

FACILITY NAME

DOCKET NUMBER

05000-

FACILITY NAME

DOCKET NUMBER

05000

9. OPERATING
MODE

N

10. POWER
LEVEL

100

11. THIS REPORT IS SUBMITTED PURSUANT TO THE REQUIREMENTS OF 10 CFR §: (Check all that apply)

20.2201(b)

20.2203(a)(3)(ii)

50.73(a)(2)(ii)(B)

50.73(a)(2)(ii)(A)

20.2201(d)

20.2203(a)(4)

50.73(a)(2)(iii)

50.73(a)(2)(x)

20.2203(a)(1)

50.36(c)(1)(i)(A)

X 50.73(a)(2)(iv)(A)

73.71(a)(4)

20.2203(a)(2)(i)

50.36(c)(1)(ii)(A)

50.73(a)(2)(v)(A)

73.71(a)(9)

20.2203(a)(2)(ii)

50.36(c)(2)

50.73(a)(2)(v)(B)

OTHER
Specify in Abstract below or in
NRC Form 308A

20.2203(a)(2)(iii)

50.46(a)(3)(ii)

50.73(a)(2)(v)(C)

20.2203(a)(2)(iv)

50.73(a)(2)(i)(A)

50.73(a)(2)(v)(D)

20.2203(a)(2)(v)

X 50.73(a)(2)(ii)(B)

50.73(a)(2)(vii)

20.2203(a)(2)(vi)

50.73(a)(2)(i)(C)

50.73(a)(2)(viii)(A)

20.2203(a)(3)(i)

50.73(a)(2)(ii)(A)

50.73(a)(2)(viii)(B)

12. LICENSEE CONTACT FOR THIS LER

NAME Earl R. Libby, Supervisor-Operations

TELEPHONE NUMBER (Include Area Code)

(914) 736-8514

13. COMPLETE ONE LINE FOR EACH COMPONENT FAILURE DESCRIBED IN THIS REPORT

CAUSE	SYSTEM	COMPONENT	MANU- FACTURER	REPORTABLE TO EPIX	CAUSE	SYSTEM	COMPONENT	MANU- FACTURER	REPORTABLE TO EPIX

14. SUPPLEMENTAL REPORT EXPECTED

YES (If yes, complete EXPECTED SUBMISSION DATE) X NO

15. EXPECTED
SUBMISSION
DATE

MONTH DAY YEAR

16. ABSTRACT (Limit to 1400 spaces, i.e., approximately 15 single-spaced typewritten lines)

On August 14, 2003, at approximately 1611 hours during 100% steady state power, Indian Point Unit 2 experienced an automatic reactor trip initiated as a result of low reactor coolant loop flow due to the trip of the 22 Reactor Coolant Pump (RCP) breaker. The 22 RCP breaker tripped due to electrical supply bus under-frequency caused by an unstable off-site power grid (Northeast blackout). Off-site power was lost and all three Emergency Diesel Generators started and energized their assigned safety buses. Main feedwater isolated and the Auxiliary Feedwater (AFW) pumps automatically started. A Notification of Unusual Event (NUE) was declared at 1625 hours, in accordance with the Emergency Plan when off-site power was unavailable for greater than 15 minutes. The NUE was terminated on August 15, at 0210 hours, when off-site power was restored. The cause of the event was a loss of off-site power due to an unstable power grid. Corrective actions to address the cause of the event included a post trip review, root cause evaluation and plant assessment. There were no nuclear safety concerns exhibited during the event and all fission product barriers remained intact. There was no impact on the health and safety of the general public.

LICENSEE EVENT REPORT (LER)

FACILITY NAME (1)	DOCKET (2)	LER NUMBER (6)			PAGE (3)
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	
Indian Point Unit 2	05000-247	2003	- 05 -	00	2 OF 4

NARRATIVE (If more space is required, use additional copies of NRC Form 386A) (17)

DESCRIPTION OF EVENT

Note: The Energy Industry Identification System Codes are identified within the brackets {}.

On August 14, 2003, at approximately 1611 hours, during 100% steady state power, Indian Point Unit 2 experienced an automatic reactor trip (RT){JE} initiated by a loss of off-site power due to a grid disturbance. The loss of off-site power (LOOP) was associated with the blackout that affected parts of northeastern United States and Ontario, Canada. The degraded grid caused an under-frequency breaker trip on the 22 Reactor Coolant Pump (RCP). The trip of 22 RCP breaker initiated a RT on low reactor coolant loop flow (1 of 4 low loop flow with reactor power above P-8, approximately 35% power, permissive set point). The plant stabilized in natural circulation and the Emergency Diesel Generators (EDGs){EK} 21, 22, and 23 started automatically and energized the 480V buses. Main feedwater system isolated and the Auxiliary Feedwater System (AFW) {BA} pumps automatically started. Certain equipment that failed to operate properly included a leak in the service water line, Technical Support Center (TSC) Diesel and Radiation Monitor R-45 (Condenser Air Ejector Discharge). The TSC Diesel did not start as expected and was recorded as Condition Report CR-IP2-2003-5203. This condition did not prevent activation of the emergency plan when required. None of the equipment issues precluded the return of the Unit to power.

No actuation of the Safety Injection System occurred nor was required as a result of this trip and no Power Operated Relief Valves actuated during this event. The Pressurizer Code Safety Valves remain closed throughout this transient. This event was entered into the Entergy Corrective Action Process under CR-IP2-2003-05176.

As a result of the blackout event, Radiation Monitor R-45 for monitoring condenser air ejector discharge failed, and a compensatory sample required by the technical specifications was missed. This event is also reported in this LER under 50.73 (a)(2)(i)(B) as an "operation or condition prohibited by Technical Specifications," and was entered into the Entergy Corrective Action Process under CR-IP2-2003-05296.

CAUSE OF EVENT

The cause of the reactor trip was a loss of off-site power due to grid disturbance. The root cause of the grid disturbance which resulted in a blackout for parts of northeastern United States and Ontario, Canada is under investigation by a joint United States and Canadian government special task force. The grid disturbance caused the main generator to have lower frequency. The 22 RCP breaker tripped on under-frequency, which resulted in a RPS logic trip of the reactor on loss of RCS loop flow.

The cause of the missed compensatory sampling for the Radiation Monitor R-45 was attributed to communication error and programmatic weakness and has been recorded as CR-IP2-2003-05296.

LICENSEE EVENT REPORT (LER)

FACILITY NAME (1)	DOCKET (2)	LER NUMBER (6)			PAGE (3)
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	
Indian Point Unit 2	05000-247	2003	05	00	3 of 4

NARRATIVE (If more space is required, use additional copies of NRC Form 366A) (17)

CORRECTIVE ACTIONS

The reactor experienced an automatic trip and the plant shutdown as designed. All emergency systems initiated as required. Corrective actions for the event included a post trip review, a root cause evaluation, and plant walkdown. No specific corrective actions to preclude loss of off-site power due to a similar event were identified.

The corrective action for the missed compensatory sampling for R-45 is being resolved as per CR-IP2-2003-05296.

EVENT REPORTING

This event is reportable under 10 CFR 50.73 (a) (2) (iv) (A). The licensee shall report any event or condition that resulted in manual or automatic actuation of any of the systems listed in 10 CFR 50.73 (a) (2) (iv) (B). Systems to which the requirements of 10 CFR 50.73 (a) (2) (iv) (A) apply includes the Reactor Protection System including reactor scram or reactor trip, AFW and EDGs. The event for the missed compensatory sample for radiation monitor R-45 for the failed condenser air ejector discharge is reportable under 10 CFR 50.73 (a) (2) (1) (B).

LICENSEE EVENT REPORT (LER)

FACILITY NAME (1)	DOCKET (2)	LER NUMBER (6)			PAGE (3)
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	
Indian Point Unit 2	05000-247	2003	05	00	4 OF 4

NARRATIVE (If more space is required, use additional copies of NRC Form 366A) (17)

PAST SIMILAR EVENTS

A review of previous occurrences when IP2 had experienced unit trip due to a loss of off-site power was performed. Within the past three years, three(3) occurrences were identified and were reported to the NRC in the following LERs:

LER 2003-004-00: This LER reported that on August 3, 2003, Indian Point Unit 2 experienced an automatic reactor trip initiated by a main turbine trip. The turbine trip was caused by an electrical disturbance associated with the 345kV North Ring Bus at the Buchanan Substation.

LER 2003-003-00: This LER reported that on April 28, 2003, Indian Point Unit 2 experienced an automatic reactor trip initiated by a turbine trip. The turbine trip was caused by a generator trip of the over-frequency relays actuated by a disturbance associated with the 345kV North Ring Bus at the Buchanan Substation and the Con Edison 138kV system.

LER 2001-007-00: This LER reported that on December 26, 2001, Indian Point Unit 2 experienced an automatic reactor trip initiated by a turbine trip. The turbine trip was caused by a generator trip of the over-frequency relays actuated by a disturbance associated with 345kV Bus W93. The cause for the over-frequency relays actuation was a failure of the blocking relay on Con Edison 345 kV feeder Y94.

As indicated in LER 2003-04-00, a corrective action has been assigned to the 345 kV System Engineer to follow up with Consolidated Edison and obtain their root cause report. This report will contain Consolidate Edison's actions to prevent re-occurrence and improve grid reliability to the Indian Point Station (Due December 31, 2003).

EVENT SAFETY SIGNIFICANCE

There were no significant safety consequences for this event because the plant systems responded as expected except as noted. No pressurizer safety valves lifted and no actuation of the safety injection system was required. There were no nuclear safety concerns exhibited during the event and all fission product barriers remained intact. There was no significant impact on the health and safety of the general public.

The loss of a reactor coolant pump is described in the UFSAR Section 14.1.6, "Loss of Reactor Coolant Flow." This event was initiated when the Unit was operating at 100 % power and is bounded by the UFSAR analysis.

The loss of power to station auxiliaries is described in UFSAR Section 14.1.12, "Loss of Station Auxiliaries." The design event as described in the UFSAR results in a loss of offsite power to both 6.9kV and 480V busses. In this event, the loss of power was per this design event and was bounded by the UFSAR analysis.

There was no safety significance for the missed compensatory sampling for R-45, because the chemistry sample before and after the missed sample had no measurable activity.